

<b>Scan Gap Settings</b>	
<b>DPI to Scan Gap = 25.4/DPI</b>	
<b>DPI</b>	<b>Scan Gap</b>
100	0.254
125	0.203
150	0.169
175	0.145
200	0.127
225	0.113
250	0.102
275	0.092
300	0.085
325	0.078
350	0.073
375	0.068
400	0.064
425	0.060
450	0.056
475	0.053
500	0.051
525	0.048
550	0.046
575	0.044
600	0.042
625	0.041
650	0.039
675	0.038
700	0.036
725	0.035
750	0.034
775	0.033
800	0.032
825	0.031
850	0.030
875	0.029
900	0.028
925	0.027
950	0.027
975	0.026
1000	0.025