

Scan Gap Settings

DPI to Scan Gap = 25.4/DPI

DPI	Scan Gap
100	0.254
150	0.169
200	0.127
250	0.102
300	0.085
350	0.073
400	0.064
450	0.056
500	0.051
550	0.046
600	0.042
650	0.039
700	0.036
750	0.034
800	0.032
850	0.030
900	0.028
950	0.027
1000	0.025